

**Change to Facility Licence Requirements for
Facility Sub-types 344, 345, and 506**

Jurisdiction	Release/Revision Date	Location of Change in this Document	Comment
AB	August 8, 2012		Initial Release

Audience: All Alberta Users

Purpose: This tip informs AB Petrinex users that a facility licence may or may not be entered when requesting a new facility identifier for facility sub-types 344 - In-Situ Oil Sands, 345 - Sulphur Reporting at Oil Sands, and 506 - In-Situ Oil Sands.

Background: Previously, facility licence numbers were not entered when requesting facility identifiers for In-Situ oil Sands facilities. Effective August 1, 2012, the ERCB now allows the facility licence number to be entered when one exists.

To update existing facilities which have facility licence numbers that have not been entered, please contact the ERCB Production Accounting Help Desk for assistance at (403) 297-8952, ext. 3 or by e-mail to pa.help@ercb.ca.

More information: Please contact the ERCB Production Accounting help line at (403) 297-8952, ext. 3 or by e-mail to pa.help@ercb.ca.